HealthCare

CSO Customer Support Operations

HOME

Field Service Bulletin No. 5

Order No.: DD+DIS082.02E

1 piece U3UQ8 MA1

ADC Compact Plus

Type 5146 / 100/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
X				X	

Please file this document in section 10 of your technical documentation

Must- Modification "Fuse Board Protection Kit" (CM+9.5146.1711.0)

This modification is a MUST – modification. The Fuse board protection has to be installed on all machines in the field.

Problem

Lead markers which have not been removed from the cassette before inserting them into the digitizer, may probably get loose and fall down on the fuse board.

This may cause severe damage in the digitizer

Reason

There is an uncovered gap between the input buffer and the cover plate of the power unit.

Solution

Install the fuse board protection kit to cover the remaining gap.

Order number: CM+9.5146.1711.0

AGFA